



Inspection Service, LLC

Assurance begins here

Phone: 813-864-7697

Fax: 813-671-1103

11705 Boyette Road, Suite 404
Riverview, FL 33569

Monday, August 3rd, 2009

Harry Sample
123 Main Street
Sun City Center, FL 33573

Imported Drywall Survey – 123 Main Street

On this day I performed a Level I Imported Drywall Survey on the residence listed above, during the course of the survey I searched for accelerated corrosion of metal components and other known Red Flags associated with the effects of Imported Drywall from China.

SURVEY AREA	RED FLAG	RESULT
Interior Air Space	Rotten Egg Odor	Negative
Air Handler Coil – Garage	Accelerated Corrosion	Negative
Electric Panel – Garage	Accelerated Corrosion	Negative
Attic (limited visual survey)	Drywall Labeling & Marking	No Chinese Drywall Observed
Plumbing Fittings – Garage	Accelerated Corrosion	Negative
Plumbing Fittings - Kitchen & Bath	Accelerated Corrosion	Negative
Electric Devices (random sample)	Accelerated Corrosion	Negative
Mirrors (throughout the home)	Deteriorated Silver Back	Negative

Without further destructive testing which would require cutting holes in the sheetrock wall and sending samples out for lab testing it is impossible to know for certain if Imported drywall exists in this home, but based on the Red Flag Survey I conducted it is my conclusion that there is no evidence of any active Red Flags associated with the installation of Imported drywall within this dwelling. Furthermore, at this time destructive sampling and lab testing of the drywall in this home is unwarranted.

More information can be found on the web at the following sites:

<http://www.doh.state.fl.us/environment/community/indoor-air/drywall.html>

<http://www.floridashealth.com/Environment/community/indoor-air/casedefinition.html>

Included for your records is a photo of your cooling coil on the day of inspection which looks normal.



Yours truly,

Joseph T. Burkeson

Joseph T. Burkeson, Certified ASHI Inspector.